


Wiring Diagram

Plug in Thermocouple Terminals



K type thermocouples with integrated spade connectors

Thermocouple Sensor Inputs

4 - K-type thermocouple inputs
Miniature style inputs



Temperature Measurement Range

0C to 1000C

Accuracy

+/- 3C

Dry Contact Input

This general purpose input can be used to monitor a switch(es) closing or opening. The input sources 12vdc at 10ma.

Surge Protection

It is recommended that a surge suppressor be used for the wall plug power adapter and the phone line.